# **Change Notice**

Changes to Production & Location for MRA, MRF & MRK Rotaries

□ Engineering□ Part Number□ Product☑ Appearance

**I.** There will be production changes for MRA, MRF and MRK switches, the miniature process sealed rotaries. The lot number on the switch will be modified to have a dot mark above the first digit. The location of production will change, and the box in which the switches are packaged for shipping will read "CHINA FACTORY" instead of "JAPAN FACTORY." These modifications will apply to standard and custom products.



Changes for Miniature
Process Sealed Rotaries

	Lot Number	Shipping Box
	Example of Lot Number without Dot Mark	
Before Changes	70	"JAPAN FACTORY" printed on side of box
After Changes	Example of Lot Number with Dot Mark Above First Digit	"CHINA FACTORY" printed on side of box

#### Notes

There are no changes to the switches' dimensions or specifications.

The location of the lot number on the switch and the location of production on the box may vary depending on the part number. Contact the factory if more details are needed.

* MR Rotaries Effected by Production & Location Changes				
MRA112	MRF112	MRK112		
MRA206	MRF206	MRK206		
MRA403	MRF403	MRK403		
* Includes Part Numbers with All Knob Types & All Knob Colors				

#### **Effective Date**

Changes to the production of MRA, MRF or MRK Rotaries will be effective May 2018.



http://www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

## **Change Notice**

### **NKK Logo Updated for MRF Rotaries**

Type of Change:		MP_FILE
☐ Engineering	☐ Part Number	- Career
□ Product	☑ Appearance	ALCOHOL:
		Changes for MRF Rotaries

2. The place of manufacture will change for MRF switches, the half-inch process sealed rotaries, and "JAPAN" will no longer appear on the switch case. In addition, the logo for MRF Rotaries will be updated. This modification will include all standard and custom devices.

	Switch Case	Identification on Switch
Before Changes	"JAPAN" on Switch Case	Older NKK Logo
After Changes	"JAPAN" on Switch Case Removed	NKK Logo Updated

### Notes

There are no changes to the switches' dimensions or specifications.

The location of the updated NKK logo may vary depending on the part number.

Contact the factory if more details are needed.

MRF Rotaries with New Logo				
MRF112	MRF206	MRF403		

### **Effective Date**

Changes for MRF Rotaries to update the logo will be effective May 2018.



http://www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435